

Crater Bench Care + Maintenance Guidelines



Polyethylene surfaces may be cleaned by washing with mild detergent in lukewarm water using a soft cotton cloth. Rinse well with clean water and wipe dry with a soft cotton cloth.

If stronger cleaning agents become necessary, follow the cleaning agent's directions, taking precautions not to expose surfaces less durable than polyethylene to stronger cleaning agents.

Do not use abrasive materials like sandpaper, steel wool or scraping tools, etc. to remove foreign substances from the surfaces of polyethylene. They can disrupt the surface texture and alter the appearance.